## だい か こうさくきかい **第21課 工作機械**

## Unit 21: Machine Tools

| No. | Word/Phrase | How to read (Hiragana) | Translation       | Note  | Example  |
|-----|-------------|------------------------|-------------------|---|--|
| 1   | 工作機械        | こうさくきかい                | Machine tool      |   |  |
| 2   | 装置          | そうち                    | Device; equipment |   |  |
| 3   | 旋盤          | せんばん                   | Lathe             | Machine to shave workpieces placed on the table while rotating them.                            |  |
| 4   | フライス盤       | ふらいすばん                 | Milling machine   | Machine to cut workpieces by moving a tool installed on the rotating shaft.                     |  |
| 5   | ボール盤        | ぼーるばん                  | Drilling machine  | Machine to make holes by contacting a drill or the like with the material fixed on the machine. |  |
| 6   | 操作盤         | そうさばん                  | Control panel     |   |  |
| 7   | コード         | こーど                    | Cord              |   |  |
| 8   | プラグ         | .ぷらぐ                   | Plug              |   |  |
| 9   | 燃料          | ねんりょう                  | Fuel              |   |  |
| 10  | ハンドル        | はんどる                   | Handle            | Parts used to open and close a large-sized door or lid or to lock them.                         |  |
| 11  | メーター        | めーたー                   | Meter             |   |  |
| 12  | ランプ         | らんぷ                    | Lamp              |   |  |
| 13  | レバー         | ればー                    | Lever             |   | レバーを下げます。  |
|     |             |                        |                   |   | Lower the lever.                                   |
| 14  | スイッチ        | すいっち                   | Switch            |   |  |
| 15  | ボタン         | ぼたん                    | Button            | Parts used to switch on; off by pushing them.   | はじめに電源ボタンを押します。<br>Firstly, push the power button. |
| 16  | グラインダー      | ぐらいんだー                 | Grinder           |   |  |
| 17  | プレス機        | ぷれすき                   | Press machine     |   |  |
| 18  | 軸           | じく                     | Shaft             | It is also called "シャフト."   |  |
| 19  | ギヤ          | ぎや                     | Gear              | It is also indicated as "ギア," "ギャー," and "ギアー."   |  |