## だい か けんさ **第24課 検査**

## Unit 24: Inspection

No.	Word/Phrase	How to read (Hiragana)	Translation	Note	Example
1	基準	きじゅん	Baseline		
2	標準	ひょうじゅん	Standard		
3	保証	ほしょう	Assurance		
4	不良	ふりょう	Defective		
5	欠陥	けっかん	Fault; defect		
6	バラつき	ばらつき	Variation	Size, weight, etc. of a product not being uniform.	
7	歪み	ゆがみ	Distortion		
8	ずれ	ずれ	Shear		
9	バリ	ばり	Burr	Unnecessary projections formed during the metal processing	バリをやすりで取ります。
				process.	Remove burrs with file.
10	ひび	ひび	Crack		
11	むら	むら	Irregularity		
12	<u></u> 漏れ	ŧ n	Leakage		
13	劣化(します)	れっか(します)	Deterioration (to deteriorate)		
14	無駄	むだ	Waste; wastefulness		
15	錆びます	さびます	To get rusty		
16	錆	さび	Rust		
17	標準化	ひょうじゅんか	Standardization		
18	性能	せいのう	Performance		
19	欠陥品	けっかんひん	Defective product		
20	ぽかミス	ぽかみす	Careless mistake	To produce defective products, invite complaints, or cause losses due to a human error.	
21	センサー	せんさー	Sensor		
22	検品(します)	けんぴん(します)	Inspection (to inspect)		
23	傷	きず	Flaw	It refers to wounds, scratches, scars, etc. on your body and chips,	
				cracks and scratches on the surface of materials or products.	
24	歩留まり	ぶどまり	Yield rate	The rate of manufactured products excluding defective ones against the total production volume.	